	OSO NE													SINE FAILURE				
PE OF A/C	UN		PLACE 1 mile West M.A.							DATE 11.4.43 TIME 1500					z	Str. O. H. S. S. S. H. S. S. S. H. E. L. H. L. H. E. L. H. L. H. E. L. H. L. L. H. E. L. H. L.		
/	A/C TYI	A/C TYPE T/Loth DH82C				No. 5804			CRAS CAT.	RASH AT. A		SEX	ME	D	X X	NIGHT	MISC	
4		N A M E RAI					K No. DUT			י וועמו			≀IES		SERIOUS		ے ا	ORK SURK
T 4	İ	Freedman, G.F. F				105173 Pp			Slightly						FATAL INJUI		LANEOU	ORERIALES
PE OF														SERIAL DO		S	2 1. 14.0	
<i>`</i> / ≿	Т Т	YPE A/F ENGINE	No.	EXTENT OF DAMAG	RE	PORT	SERIAL No.	DAT	E	ног		JRS FLOWN BY PI			TOTAL LAST			1/8// /
2			DH82C #							INST.	NIGHT		ON TYPE		SOLO	LAST 6 MOS.	STA	1.6/ /
GORY	G	G/Major 7590/85485 Totall			lly												10	15/24/
CATEG	Ş	SIGNAL NO & DATE UNIT NO. & A. 235 11.4.43				E COM. N		No. & E	o. & DATE		REPORT		FILE		DATE		п	\$\fr\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\

DUTY ON WHICH ENGAGED: COURT OF INQUIRY, INVESTIGATING OFFICER Practicing sequences 6.7.8 and 9. OR COMMANDING OFFICER'S REPORT: INVESTIGATING CFFICER'S FEPORT NATURE OF ACCIDENT AND STAGE OF FLIGHT. DATE: 21-4-43. Spun off gliding turn in circuit COMPOSITION: and A/C hit ground. F/L Johnston, A. #31 E.F.T.S. Dellinton, Alta. RECOMMENDATIONS: It should be impressed on pupils that they must keep themselves up to a high degree of fitness. PRIMARY CAUSE: Pilot's activities on the previous night might poss-18. Loss of control. ibly have contributed to his being less alert in view of his experience. Allowing airspeed to get too low in gliding turn & attempting to correct incipient spin with ailerons. ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER NiL. CONCLUSIONS OF A.I.B. This accident was due to the inability of the student pilot to maintain or recover equilibrium by sensory aids. SECONDARY CAUSE OR CONTRIBUTING FACTORS: 23. Spirning. 14. Misuse of controls. RECORDED BY DATE)21. Inability to maintain equilibrium. CHECKED BY DATE R.C.A.F. FORM L20 REO. 1247 10M-15-11-41