γ	PILOT OTHERS		RFRAME	FAIL	URI				E FAIL	URE	
$\circ$	UNIT #11 E.F.T.S. COM. Cap de la Madeleine #3 T	li li	M.A.				11	_	3   TIME		1 / 6 /
>- F	A/C TYPE Finch II	N			CRAS CAT.	<sup>H</sup> C.1/2	SE X	ME	DAY	NIGHT	NEW.
_‡	NAME	RANK	No.	DUTY		וטנאו	RIES		SERI	ous	S C E L L A L L S S L L S S L L S S L L S S L L S S L L S S L L S S L L S S L L S S L L S S L L S S L L S S L S L S S L S S L S S L S S L S S L S S L S S L S S L S S L
PE OF ENGINE	Daigle, L.J.	LAC	R170715	7 PP		Nil					S O O S SERVICE STATES
}	TYPE A/F No. EXTENT & ENGINE No. OF DAMAG	REP	ORT SERIAL	DAT	Е	НО	URS FLO	WN BY	PILOTS		-i 1/6//
	Finch II #4516 Seriousl Kinner 6005/1343 Nil	у .	RM No.			2 Nil	ON TY	or <b>o</b> D	TOTAL UAL SOLO	6 MOS.	F T TAKE
GORY											I O SIL A

$\longleftrightarrow f \to \to \to \to \to f \to $		<b>)</b> ) ) )	) <b>)</b>
Seq. 6,7,8.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:	D.14	)
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Landed too far up field, trying to change direction at high speed resulted in ground loop.	DATE: COMPOSITION: LO/FS		)
)	RECOMMENDATIONS:		)
PRIMARY CAUSE:  29 Overshooting  OVERSHOT.			)
) OVERSHOT.	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER		)
)	Log Book Endorsed		)
secondary cause or contributing factors:  38 Ground Looping			)
32. Pilot error	RECORDER	D BY	ATE )
The state of the s	CHECKED	BY D	ATE )
			), ), )