Q/	PILOT OTHERS	AIR	FRAME	FAILi	JRE		f		FAILU		LING OF THE PROPERTY OF THE PR		
OF A	1081 $x \in \{0\}$ Solia group   008   1081 $x \in \{0\}$ Solia $x \in $												
PΕ											M INSTS		
F	TYPE Hurricane XII	No.	5 <b>46</b> 0		CRASH CAT.	C.2	X X	ME	DAY N	пент	いいし / ムラ /		
	NAME	RANK	No.	PUTY		ענאו	RIES		SERIO		E ORL'S		
	Taillefer, J.H.J.	FS	R77187	P	Nil				FATAL 1	NJURY			
ш										cn	オードペケー		
<u>z</u> 0 z									CARI	D	12/37		
ld L									J.		1 / 4/		
PEO									V	<u> </u>	1 1/3/2		
TYF	TYPE A/F No EXTENT		RT SERIAL	DATE		но	URS FLO	WN BY PIL	OTS		1 1/8/2		
	& ENGINE OF DAMAG				INST.	NIGHT	ON TY	PE T	OTAL SOLO	LAST T	S TAKE OF		
H	Packard 19294/A.414 Sli	gucty			51	18		24 13			A AK		
F.	1 1 1									I	*I 1/2*/		
093	Hurricane 5460 Slight	:ly											
й		DATE	1 2011	No. & DA	'	REPO		FILE	DA	T 67	1 X&		

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	D.14 #11	,
Army co-op exercise	OR COMMANDING OFFICER'S REPORT:	** * ***	
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Flying at 7000 when engine develop what was afterwards found to be mag		m/p/s	
trouble. Engine stopped firing & p chose good field & did a procedure forced landing, giving base his pos over radio. There was no warning i	ition MENDATIONS:		,
	lot Magneto rotors to be checked o	n P.30's	, )
ARXIMAXXIADSEX checked controls prior landing & could not rectify trouble			)
Tanding & could not rectify trouble	•		)
PRIMARY CAUSE	ACTION TAXABLE		)
54. Engine failure in the air	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER		)
(Port magneto intermittent) (Stbd. magneto unserviceable)  17. FORCED LANDING SECONDARY CAUSE OR CONTRIBUTING FACTORS:	7 Nil		)
26. ENGINE TROUBLE- 26	DECORDED	BY DATE	)
	CHECKED B	Y DATE	— )
			, ,