\ \{\}	CH OF RECEIVED AND AND AND AND AND AND AND AND AND AN	12 12 12 12 12 12 12 12 12 12 12 12 12 1		STREE STR	51015 6	\$ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	kir, fie k 8 Hirt / 55 k 8 Hirt / 55 k	04/ 0 261 / 10	olitika Olitika	0) (6 6 (7)	1. (515. 1. (515.)	140. 5 245. 25	The the	Micci, ind
أد	PILOT	OTHERS			FRAME					ENG		FAIL	<del></del>	
TE OF A	UNIT #34 E Assini	сом. #4 Т(	TC PLACE 2 miles east of M.A.					DATE 4.5.43 TIME 0755						
	A/C TYPE Cor	nell I		No.	1059	99	CRASH CAT.	H P	SE X	МЕ	0	X	NIGHT	15 0
_		NAME		RANK	No.	DUTY		ענאו	RIES			SERI	ous	A L C
	Wiltsh	nire, J.K	[. ]	70.	111225	FI	Nil					FATAL	INJURY	
	Kerr,	-	i	AC :	167234	12 PF	Nil							A N E S
INCOLUSE.							e) 1: (201)					CAI SERIA		S O S
			1						The state of the s	<b>t</b> —		v.	\	
f	TYPE A/F	N	EXTENT	REPOR	T SERIAL	DATE	_	НО	UR <b>İŞ</b> FL	OWN E	BY PILO	oTs		1 1 1/
	Cornell	No. 10599	OF DAMAGE Nil	FORM	No.	DATE	II	NIGHT	ON T	SOLO	TO	TAL SOLO	LAST 6 MOS	.[][⊣ [/₃
1	Ranger	27427	Slightly	7	(Wi]	tshir	e) 12	257	-	101	58	1100	)	그러인/>
2					(Ker	r)	4	-	20	17	20	17	ļ	J*!   /
	SIGNAL NO	. & DATE	UNIT No. & D	ATE	СОМ	. No. & D	ATE	REPOR	₹Т	F	LE	   D	ATE	
Ì	Nil					į								111
				NAT.	URE	ΟF	ACCI	DENT						

Training	OR COMMANDING OFFICER'S REPORT:  D.14 #3	
NATURE OF ACCIDENT AND STAGE OF FLIGHT:  Shearing of oil pump drive shaft caused engine failure after take off. Instructor executed satisfactory forced landing w/o further	DATE: COMPOSITION:	
damage to a/c.	RECOMMENDATIONS:	
33. Technical defect (Pressure oil pump drive shaft broat keyway, inside of oil pump gear Cause appears to be due to flaw in material, although it is thought the keyway may be deeper than necessulting in weakness at this point	* ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  hat  Nil  ssary,	
SECONDARY CAUSE OR CONTRIBUTING FACTORS:		
54. Engine failure in the air	RECORDED BY	DATE