	Archital	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	16 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	STATE STATE	Nats It AND IT	15 (15t)	Ser Carlotte	10 10 10 10 10 10 10 10 10 10 10 10 10 1	RIMET CUT	35. 35	125 / N	646 K	RS CHO		
-/ <b>√</b> /√\೪ _	PILOT	OTHERS			FRAME		_URE			ENGI	NE F	AILU	JRE	_	**************************************
YPE OF A	High Ri	сом. # <b>4</b>	TC PLA	es o appr of M.A.	1/4 mil	а <b>t Н</b> РАТ Н.О.	tipate 6.5.43		TIME 2255 0-105-21		The state of the s				
φ / Ι⊢ΙΑ	YPE Corr	ell II		No.	10521	L	CRASH CAT. B		SE X	ME	D,	AY !	NIGHT X	0 51	/ (2) /
$^{\prime\prime}$ $^{\prime\prime}$		NAME		RANK	Nφ.	DUTY		ULNI	RIES	S		SERIC	ous	]>  [ [	ORKE JIRK
·/  [	Leslie,	J.C.		PO	J23004	FI	Sl	ight]	Ly		F	ATAL	INJURY	S	
, >   -	Cockx, S.J.R.			Cpl	R77897	PP	Sl	ight]	L <b>y</b>			2		(f) Z	[x <sup>2</sup> ]
PE OF ENGIN												CAR SERIAI			01/10 11/10/14/0 22/14/0 14/14/0
[ //}[	TYPE A/F	No.	EXTENT	REPO	RT SERIAL	DAT	F	нс	URSF	LOWN E	BY PILC	TS		111	/ 67/
1 1 L	& ENGINE Cornell		of damag		M No.	DA.	INST.	NIGHT	1	TYPE   solo	TO:	TAL	LAST 6 MOS.	[ <u>_</u> ] ⊣ ].	(x <sup>6</sup> / /
	OULHOLA	<u>   ) </u>		<b></b>	-		53	76	9	207	82	753		]-[6]	tight
φ	Ranger 6	-440C-5	27295	Se	erious		5	4	24	25	24	25		HTO	7 X Y
ATEG	SIGNAL No.		UNIT NO. &	DATE	COM.	No. & 1	DATE	REPO	RT	FI	LE	DA	ATE	"   	
[ / ] J-	T.95   7	.5.43		N A	TURE	O F	ACCI	DENT	·····						—\``\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
	V /03 / 12 / 15 / 15 / 15 / 15 / 15 / 15 / 15	9 (4 8	0/0/0	11 ( 51 )	2/3/2/		0/0/0/	) so (s	\v\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	2 62 (1	2 SZ	97 6	\n^\v\\v\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		30 ere 25

	<b>,,,,,</b> ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	)
	RY, INVESTIGATING OFFICER	
Routine circuit Sequence 25. OR COMMANDING	OFFICER'S REPORT:	
NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE:	D-14 # 4.	r
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Turning into wind encountered sleet COMPOSITION: and ice. Instructor took control and	LFM /AOP/ + 63/NK/1/4/	<i>-</i>
engine quit at same moment. Hit some-		
thing after putting on landing, bounced and went up on its nose and over on		
back. All switches were shut off. RECOMMENDATION	NS:	
Occupants were trapped in A/C as coupe tops were crushed in.		
PRIMARY CAUSE:		
19. Bad weather.		
4. HEAVY ACTION TAKEN:		
	r (B) Technical (C) Other	
SECONDARY CAUSE OR CONTRIBUTING FACTORS:		
54. Engine failure in the air. 41. Hitting obstructions.	RECORDED BY DATE	
37. Overturning.	RECORDED BY DATE	
	CHECKED BY DATE	_
	3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	`