U PILOT	AS AS LI ON		AIRFRAME FAILURE					Ling (11ti)	ENGINE FAILURE				Wiscep, Or		
UNIT NO.33 E.F.T.S. COM.				PLACE 1 mi. south Grayburn, Sask.				DATE 18-5-43 TIME 1655 H.O. FILE 1700-10626					/ .5./		
> \ \/C	A/C			No. 10626			RASH AT A SE x ME				-	NIGHT	4 I S C	MERT!	
	N A M E RAI			No.	DUTY	RULNI Y			RIES	IES			SERIOUS		DRATA PA
Shear	Shearer, G.A. So			145160	5 FI	Fatal						ATAL	אאטנאן	S	RY C
i				C 1556910 PP			Fatal					2		1:14	/xx*/
Z U U U U U U U U U U U U U U U U U U U							1909					CAR SERIAI			O'TO TO T
> <u> </u>	TYPE A/F No. EXTENT		REF	PORT SERIAL	DAT	DATE H		НО	URS FLOWN BY PILO			· · · · · · · · · · · · · · · · · · ·		1 1 1	/ 87
& ENGI	IE .	Total	E FC	ORM No.			INST.	NIGHT	ON T	YPE solo	TO	SOLO	LAST 6 MOS.	" ⊣	1.46/
Range			31				5 2	10	133 20	163 10					11, 14, 1
ш	No. & DATE	UNIT NO. &	DATE		. No. &	DATE		REPO	RT		LE	D/	ATE	"	

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER D. 14 #15
) Routine instructional flight	OR COMMANDING OFFICER'S REPORT:
) NATURE OF ACCIDENT AND STAGE OF FLIGHT:) A/C observed flying low and) gradually losing height, the A/C was flying South. It turned North	COURT OF INQUIRY COMPOSITION: LOC / AC C /
) and suddenly dropped nose first	F/O Jarratt, W.D. #33 E.F.T.S.
)	RECOMMENDATIONS: NiL.
) PRIMARY CAUSE:) ·
, 18. Loss of control	
, 19. OUT. OF CONTROL	
(19)	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER NIL. CONCLUSIONS OF A.L.B.
	AGREE WITH THE FINDINGS. WHILE THE EVIDENCE OF THE ONLY EYE WITNESS WAS
	AVAILABLE, THE EVIDENCE OF THAT WITNESS AND THE PROXIMITY OF THE CRASH TO THE AUTHORIZED FORCED LANDING FIELD INDICATES THAT THE A/C MAY HAVE
OFFICE AND ADVICE OF THE OFFICE AND ADVICE OFFICE AND ADVICE OF THE OFFICE AND ADVICE OFFICE AND AD	BEEN MAKING A FORCED L NOING APPROACH, AND STALLED WHEN TURNING AT A LOW ALTITUDE. UNFORTUNATELY THE F.87 WAS NOT COMPLETELY FILLED OUT AND
SECONDARY CAUSE OR CONTRIBUTING FACTORS: 22. Stalling.	THERE IS NO INDICATION IN THE F. 17 OR IN ANY OF THE EVIDENCE AS TO THE OBJECT OF THE FLIGHT, OTHER THAN THE FACT THAT SGT. SHEARER WAS CONTINUING HIS INSTRUCTION OF LAC. SIMPSON. THE INSTRUCTOR HAD JUST COMPLETED
25 - Inexperience	A COURSE AT NO. 3 F. I.S. AND WAS RECORDED BY DATE
)	ASSESSED "C (ELEM.) AVERAGE. AVERAGE INSTRUCTIONAL ABILITY. HARD WORK- ING AND SHOULD DEVELOP WELL". HE HAD ONLY 29 HOURS EXPERIENCE AS INSTRUCTOR
R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41	SPREAD OVER 14 DAYS. THE ACCIDENT MUSTHECKED BY DATE) THEREFORE BE ATTRIBUTED TO INEXPERIENCE.