			25 / 24 / 150 / 104		RAME	FAIL			140/66	N. C. L. L. C. L.		NE F	ATL U	· · · · · · · · · · · · · · · · · · ·	
A/C	PILOT	OTHERS		AUSE				IDE	V T S						T KATO /
PE OF		E.F.T.S.		PLACE		Inn	isfa	.il		H.Q. S	9-5- FILE 1	43 ¹ 100-	IME 07		MENTALE NEW THE REAL PROPERTY.
TYP	A/C	nell II		No.	15041		CRASI CAT.	С		SE 2	K ME	DA	X Y	NIGHT	
		NAME	1	RANK	No.	DUTY		1	NJUF	RIES			SERIC	บร	1 0 0 5 18 X
	Souths	ate, R.J.	L	AC 13	99839	PP		Nil				F	ATAL	YRULNI	
OF ENGINE													CAR		Supply Su
/PE					T -		<u> </u>				51VN 5		TC		1 1 / 8 /
ΤY	TYPE A/F & ENGINE	No.	EXTENT OF DAMAGE		SERIAL No.	DAT	11	INST	NIGHT	ONT	TYPE	TO	TAL.	LAST 6 MOS	171 . 1 / .6: /
	Cornel	1 15041	Slight					_		BUAL 8	50LO 6	20	5010	6 903	1 101/25/
EGORY	Ranger	6-440-C-5	37067/65	584	Nil			_							コート トノスペン
TEG	SIGNAL N	O. & DATE	UNIT NO. & 1	DATE	СОМ	No. & 1	DATE		REPOF	₹Т	FI	LE	D.	ATE	THE SAN AN

)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFIC	<u>ER</u> +	
)	Flying practice solo.	OR COMMANDING OFFICER'S REPORT:		
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT: Engine cut at 2000'. Rapid cockpit check. Tried to restart engine by switching on Master Switch, pumpi wobble pump and pressing self starte and on failure of this tried diving with same result. Force landed in field and broke left wheel. Fuel	D-14 # COMPOSITION: FE //	36. Estem/pls/MID	>
ı	gauge registered between $3/4$ and full	11.		
,	PRIMARY CAUSE: 33. Technical failure. Faulty left gas gauge led pilot to believe he had more gas than was actually in the tank. 18. Misc. Technical (8)		THER	-
	SECONDARY CAUSE OR CONTRIBUTING FACTORS: 54. Engine failure in the air. 26. Engine Trovale 26 ACCIDENTS		RECORDED BY DATE	_
	R.C.A.F. FORM L20 REQ. 1247 10M-15 11-41		CHECKED BY DATE	-
))))))))	ì