

	)))))))))		) ) ) )
DUTY ON WHICH ENGAGED: Test flight after assembly.	COURT OF INQUIRY, INVESTIGATING OFFICER		
	OR COMMANDING OFFICER'S REPORT:		
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Take off in cross wind, A/C developed	DATE:	AMG- 2	)
a vertical turn to the right, right	decimi ostiton:	•	)
) lower mainplane scraping the ground.			)
throttle was closed A/C flipping over	r		
to the left, left wing striking the ground and A/C overturning.	RECOMMENDATIONS:		)
)			)
PRIMARY CAUSE:  33. Technical defect.			)
Aileron control wires were crossed			•
during assembly of A/C.			3
ACTION TAKEN:			,
CONTROL. 14	(A) DISCIPLINARY (B) TECHNICAL (C) OTI	HER	)
			)
)			
)			)
SECONDARY CAUSE OR CONTRIBUTING FACTORS:			)
37. Overturning.			
}		RECORDED BY	DATE
			)
		CHECKED BY	DATE )