

Dual cross-country flight to	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:
Kitchener, Ont. NATURE OF ACCIDENT AND STAGE OF FLIGHT: Engine started running roughly and pilot landed A/C.	DATE: COMPOSITION: D-14 #73 COMPOSITION:
))	RECOMMENDATIONS:
PRIMARY CAUSE: 54. Engine failure in the air. Failure of rocker bracket bolts on No. 4 cylinder head.	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
))	NiL.
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
)	RECORDED BY DATE
R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41	CHECKED BY DATE