Q	CEC CO CONTROL		IRFRAME		ARITOR E	1340/4		ENGI		STA KIND	7
PE OF A	UNIT #35 E.F.T.S. COM. Neepawa 2	PLACE 1/4 mile NW of M.A					DATE 19.5.43 TIME 2330				
17	TYPE T/Moth		No. 1250		CRASH CAT. C		SE X	ME	DAY	мібнт Х	To so were
٦	NAME	RANI		DUTY		ענאו	RIES		FAT	SERIOUS	
E OF ENGINE		Sgt LNA			Ni Ni					CARD ERIAL NO.	SEOUS OTH
٦ -	TYPE A/F No EXTENT		REPORT SERIAL			HOURS FLOWN BY P			/ PILOTS	6	± 1.1173
	a engine No. of Damas T/Moth 1250 Slight	E F	ORM No.	DAT	II.	NIGHT	ON T	/PE	TOTA		
SORY	G. Mjr. 81529 Nil				14	30 2	45 18	219	135 2 19	266	1 0 m 47/6
CALEC	SIGNAL NO & DATE UNIT NO. & A.218 20.5.43	DATE	сом.	No. & E	DATE	REPOF	<u>т</u>	FIL	E	DATE	

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	
Dual instruction.	OR COMMANDING OFFICER'S REPORT:	
	D-14. # 66.	
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:	
Sgt. Pepper, however, was caught downdraught which dropped him from	in COMPOSITION: 11 For A / 1. Left	
1000' to 200', with A/C practical	ly neonah	
stalled, during his cross-wind ap Despite full throttle and A/S of	80 m.p.h.	
he was unable to maintain height.	andrecommendations:	
decided to land in a large field	111-	
uminated by moon. It was a ploughtield and A/C turned over.	neu	
PRIMARY CAUSE:		
47. Woather.		
FORCED LANDING		
LANDING -	AGTION TAVEN	
	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
(1/	NIL	
<u> </u>		
A STATE OF THE STA		
SECONDARY CAUSE OR CONTRIBUTING FACTORS:		
37. Overturning		
	RECORDED BY	DATE
	CHECKED BY	DATE
	•	