ņ			RERAM			Silvino Pr		NGINE			
F A		CAUS	S E S LACE	OF A	ACCIDE	NTS	DATE 7	^ F 4	TIME	7 000	7 - Kritor
PEO	#4 TC		M.A				H.Q. FIL	2.5.4	00-AS	1820 -172	1 1 1 / .6: /
TYF	A/C TYPE Oxford II	No	°. AS.	172	CRASH CAT.	В	SE	ме Х	DAY	NIGHT	S MEN
	NAME	RANK	No.	DUTY		אטנאו	RIES		SER	lous	A C DRAFTER
	Smith, N.R.		13323		Nil				FATAL	INJURY	
固	Comber, N.		13350		Nil						E Z CHER
NGINE	Brown, R.A.	AC2	u1973	<b>21</b> Pas	s Nil					.L	1 191 <i>/3</i> %
岸山	1	<u> </u>								AL No.	1   / % <sup>*</sup> /
PE OF	,		-							人	ナナコノギン
7	TYPE A/F No EXTENT		ORT SERIAL		-	нос	JRS FLOV	VN BY F	ILOTS		1 1 1/8//
	a ENGINE   OF DAMAG	GE FOR			ļļ.	NIGHT	ON TYP		TOTAL	LAST	STA TATE
	Oxford #AS.172 Seriou	.8			34	30		20 <b>1</b> 3			- A (A)
<b>≻</b>	Cheetah X P.1674 & S.A15	9146	Nil		10	5	17		5 50		
GORY	0.000		1122								H O F T T T T T T T T T T T T T T T T T T
Ψ. H	SIGNAL NO. & DATE UNIT NO. &	DATE	co	M. No. & E	DATE	REPOR	т	FILE	ī	DATE	
ΰ	T.83 12.5.43			:							

	DUTY ON WHICH ENGAGED: COURT OF INQUIRY, INVESTIGATING OFFICER	)
ì	Dual instructional flight.  OR COMMANDING OFFICER'S REPORT:  D-14 # 10.	)
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT. DATE:	
ì	A/C to swing to port when he had attained	)
)	an I.A.S. of 60 m.p.h. He attempted to correct with opposite rudder and	)
)	A/C bounced off ground and again swung	)
)	to port. This developed/anvicious RECOMMENDATIONS: ground loop and u/C collapsed.	)
)		)
ì	PRIMARY CAUSE:	
)	9. Swinging. /2. Swing	)
ì	,	)
)	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
)	(A) Instructor interviewed and warned with regard	)
)	to his future performance.	)
)		)
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:  38. Ground loop.	)
)	32. Pilot error. RECORDED BY DATE	-
)		)
)	CHECKED BY DATE	. )
Į		) )