	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	6/65/6	63/62/	  s`/.	\$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	₩ N	) A6/	45/ AD	N3/N2/	A) AO	39/30/	37/36/	35/30/	23/22/27
2			·	A	CCIDE	NT C	LAS	SIFI	CATION			T.W.F		<del>///</del> >
~ \ \	UNIT 9 B.& G.		PLACE					DATE 13-7-43 TIME 1025						
1	Mont Joli,		Ma	ain Aerodrome				H.Q. FILE 1100-16-96				2/2/		
	A/C TYPE	-	NO.			CRASH CAT.		S.E.	M.E.	DAY	NIGHT	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		
/ 1	Battle	get) 10		96			C 5	x		х		OMM AND		
	PERSC	RANK	NUMI	BER DUTY		Y INJURIE		IES		SIGNAL				
<b>→</b> >	Dilworth, A.J.			P/0	J244	27	Р		Nil		NO		DATE	$H'//_{i}$
7/1	Gagnon, S.			•	C2 R2017		DO_	N	il	1		T•54	14-7	
——————————————————————————————————————		Marryatt, D.E.			R105	644	MTD	N	il			D 14 (REVISED)		HHNOM
-/2	Craig, J.J.			ACl	R114	424	24 MTAs		Serious.		No.		CHECKED	I LOING
1												3 1		Z T T T T T T T T T T T T T T T T T T T
	E O F				-									
· /	>				-							4		STAG LANDING
$ \lambda$	F											4		STAO STAO STA
2	ENGINE							HOURS FLO			Y PI	PILOTS		- m - 46/
	Merlin III   119820/5289			Sl	ight	INST	. N	NIGHT SOLO		DUAL		SOLO	DUAL	
	>	-				15		7	101	1		165	107	FLIGHT STRIKE
	7 C C C C C C C C C C C C C C C C C C C	<del> </del>				1 1	+	<u></u>	<u></u>			10,7		T STATE
														1 10 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
-/o/	CAT									1				1 1 1 340
		, , , , ,	<del>, , , ,</del>		CCIDI	, ,	<del></del>		CATION		7. 7	7. 7.	/4 /:	72 /2 /5 ·
	/1/3/1/0/	(1/1		\`\ \\	1/3/	,,,5	/,6/	1,10	0/0/20/	1 22	23/2	75/20	27/28	19 20 ALI IN

PURPOSE OF FLIGHT: TECHNICAL OFFICER'S REPORT: 700/x00/100 Scheduled Drogue Exercise Ni 7 NATURE OF ACCIDENT: ) Battle had just completed exercise COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: and had taxied up and turned off No. FINDINGS: SUMMARY No. 1055 2 runway. A C.P.R. Lockheed was tax-) iing in front of him, preceeded by a Failure on part of pilot to stop aircraft when truck and roller engaged in rolling he saw the truck in his path, possibly due to taxi strips. Lockheed turned off to partial brake failure; a contributory cause was right on reaching hangar tarmac and the lack of a flag or other prominent marking of ) by the time pilot of Battle was aware the vehicle and that this pilot had not been of position of truck collision was advised that the rolling operations were in inevitable. Propellor struck cab of progress. ) truck injuring M.T. Assistant. CLASSIFICATION: Warning signs or flags to be displayed when runway 2. Hitting obstructions or taxi strip work is in progress. CONCLUSIONS OF A.I.B. Agree with findings. SECONDARY OR CONTRIBUTORY FACTORS: 32. Pilot error ~ **ACTION TAKEN:** R.C. A. F. L 20 (REVISED) 7M-4-43 (3202) K.P. 5051 H. Q. 885-L 20 C. C. LTD. 7084-4