

PURPOSE OF FLIGHT:

Flying training

NATURE OF ACCIDENT:

A/C 4562 turned left and started to cross runway after landing. A/C 4775 on landing did not see A/C 4562 and on opening throttle to clear runway struck tail assembly of A/C 4562.

CLASSIFICATION:

~~45. Collision~~

6. Collision

SECONDARY OR CONTRIBUTORY FACTORS:

~~24. Carelessness~~

TECHNICAL OFFICER'S REPORT:

Nil

TCA/CT/ACC
TCA/XX

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

ACTION TAKEN:

F.O. Geggie admonished.