_		ACCIDE	NT CL	ASSIFI	CATION	DATE . 7	/3 TIM	E 1925	
	unit 6 E.F.T.S. com.	PLACE				H.Q. FILE			1 Y /
	11.11.00 1.11.01.			OBACH.	T		11(0-4		181//
	A/CTYPE T/Moth	No. 499		CRASH CAT.	B C	x	li li	x	COMMAND
	T/10th	510	כנ		· · · · · · · · · · · · · · · · · · ·				
İ	PERSONNEL	RANK NUMB	ER DU	TY	INJUR	IES	SI	GNAL	
Ì	Lewtas, L. (GF)	LAC 18022	266 _ I	P Ni	1		NO.	DATE	H/
1	Brown, D.G.	IAC R192		P Ni	1	***************************************	A48	3.7	1.Yz
l								(REVISED)	3 0 Z
l					•		No.	CHECKED	TEI/,
,							1	$\perp \mid X \mid$	Z I I FORCE
								Io• 5	10 10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
-							1	10 • 0	1 " 1 / .0
	ENGINE ENGINE NU			HOUR			PILOT		-  ™  '^e
	G. Mjr. 7459/87307 Sl	ightly	INST.	NIGHT	SOLO	TYPE	SOLO	DUAL	1-1-6
	7.70 (0.70 A) C1	5 mln + 7 mr	:20	_	5	12	5	12	FLIGHT
)	G. Mjr. 7438/87242 S1	TEUCTA	:15		6	$\frac{1}{16}$	6	16	T SAN
5									] <b>K</b> %

	• / • • • • • • • • • • • • • • • • • •	)					
Solo practice.	TECHNICAL OFFICER'S REPORT:						
NATURE OF ACCIDENT:  1 LAC Brown in 5103 collided, nose on,	with COURT OF INCHIBY OF INVESTIGATING OFFICERS	)					
A/C 4990 on landing run. LAC Brown states that his windscreen was badly clouded with oil, and when landing in	ito	)					
the setting sun, it was very difficul see. He did not see A/C 4990 until the A/C collided. LAC Lewtas states that	che two common c	) <b>)</b>					
) he saw A/C 5103 approaching, he brought his A/C to a stand-still to allow the incoming A/C the right-of-way. He was unable to							
) manoeuvre out of the way in time to a collision.	void	ı					
CLASSIFICATION:  15- Collision.	)	,					
) 6. bellisión (6)	<i>,</i> )	ı					
SECONDARY OR CONTRIBUTORY FACTORS:	)						
25. Inexperience.	ACTION TAKEN:						
R.C.A.F. L 20 (REVISED)	Log Book endorsed "Inexperience" and student to be flight tested.						
) 7M-4-43 (3202) K.P. 5051 H. Q. 885-L 20	Pilots instructed to land with coupe tops open.						