\	UNIT WO. TO T. F. F. S. COM. PLACE 3 mi. S.E. of Vo.											
ان	Pendleton,		LACE 3	m1.	čnt		وتقلته	4,Q, FILE	1700-9683			
> ⊨	Tiger Loth		2	no. 96				S.E. X		DAY	NIGHT	OMMAND
Ź۴	PERSONNÉL		RANK	RANK NUME		DUTY	INJUR		ES	SIGN	V A L	
f) offgit, D.E.		'5	F/S F110		FI		Wetal		No.	DATE	
┪	Stevens, J						Severely				1 <u>.</u> ľ/	
							Die	Died 2330 hrs.		D 14 (R	D 14 (REVISED)	
Ļľ							25-7-43			No.	CHECKED I	O C CEO
LIND										9		Ct.
Ч										_		1
TYPE							-			Мо.	.67	TAG LADY
ŀ	ENGINE	(S)			OUR	OURS FLOWN BY		PILOTS		Ⅎ℡K℀⅀		
ı	G. Mjr. IC 12883/89093		To	Total		ST. NI	IGHT		TYPE		TAL	ココノぶ
					ļ			SOLO	DUAL	SOLO	133	
EGORY		40000			55 5	5 6	39 2	68 <u>1</u> 23	102 28	803 23	28	
CATE		-			 							
رٰ	L			CCIDE	<u>II</u> ENT	CLAS	5 S 1 F	ICATION				 ~

) PURPOSE OF FLIGHT: TECHNICAL OFFICER'S REPORT:) Cross-country Richmond-Winchester. No technical failure involved. Final Navigation Check NATURE OF ACCIDENT: On cross country and 3 miles off COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: course, A/C circled farm house then FINDINGS: dived or glided to 100' over the SUMMARY No. 1082 house, failed to gain height to clear Low flying with reckless disregard of flying trees 450 ' from house, stalled about instruction and/or common sense. from ground. CONCLUSIONS OF A.I.B. A/C with instructor and pupil on an authorized cross country navigation exercise deliberately engaged in unauthorized low flying, stalled near the ground and crashed. Instructor was probably so interested in looking CLASSIFICATION: at his relatives in the yard of the Armstrong home that he failed to notice his aircraft reach the 16. Unauthorized low flying or stalling speed until too late to prevent the crash aerobatics. and being so low he was unable to regain control. SECONDARY OR CONTRIBUTORY FACTORS: ACTION TAKEN:) 7M.4.43 (3202) K P 5051 H. Q. 885.L 20