			43/54/	)))	))))	) 10 13		) ,5/hb	))))	) b) b°/	39/30	10/30	35/31/	32/32/	2)
72/	木	ACCIDENT CLASSIFICATION													
~ \ \	( ل	UNIT 36 S.F.T.S.	COM.		PLACE 9								1400	] / /	
- /	ان	Penhold	Penhold 4			Low flying area					H.Q. FILE 1100-15-15			]。[//	12
) /	1₹	A/C TYPE Oxford II			NO.	515	CR CA	ASH	A	S.E.	M.E.	DAY	NIGHT	COMMAND	/\
ブン	<b>1</b> 5	OXIOI 0 11		İ	-	-/-/		•			l x	x	1		1
	뷡				<del></del>			<del></del>			<u> 1                                   </u>	SIGN	<u> </u>	<b>∮</b> ∤ ∕	7
<b>&gt;</b>	]⊦	PERSONNEL		RANK	+		DUTY		IRULNI		NO.		DATE	<b>IJ</b> ∕∠	
)/	1	Elliott, Al.		FO	642		FI		Slightl		_		2	$\square \angle$	/ v
7	仜	Glover, J.A.		CPI	R6425	6	PP	<u> </u>	Slightl	. <b>y</b>	_  _	T131	6.7	],[ /	/ <u> </u>
<b>~</b> >	1				<u> </u>							D 14 (RE	VISED)		
-\^n	علا				<u> </u>						No.		CHECKED		'HOING
	FIN										2	2	M	(60)	ÿ/ / <del></del>
) /	1ะ													<b>-</b>	.6/
72	1 2								17			,		TAXIN	
	<b>∤</b> ⊱											6		151/.02	/ / - :
, ,		ENGINE ENGINE NUMBER (S)					HOURS FLOWN BY					LOTS			
1)/	1	Cheetah X A159383/RC262 S1			light	INS	T NI	NIGHT		ON TYPE		TOTAL		AGE OF TAKE	./ /
7	亻		45/RC182						sdrb '	DUA		sot of	DUAL	OF FLIG	
7	Į۶ٍ					9.	<u> </u>	144	1092	. 49		1129	84_		
10	្ត្រ					2:	<u> </u>	-4		3	4	85	103		
1/.	<b>]</b>									<del>                                     </del>				1 N	340
70	1>	J			CCIDE	NT	CLAS	SIF	CATION						(\$) (s)
	<u>/</u>	/0/0/0/0/0/0/0/	0/0/0	/5/	2/3/	<u> </u>	5/6/	1/0	/3/2/	2 / 22	23/20	20/20	12/20	10/30/	ari n
H⁄	~		$\mathbb{Z}\mathbb{Z}$	$\mathcal{K}$		آدان		ſχ	كأكأك		آداد	أدأد	اداد	عاداد	
L'] '	'[_	감작가작작가	1  1	/ /	<b>`</b>   <b>'</b>	\L 1					1 . 1		7   7	-1 -1	

	al concentration of the contraction of the contract	- (
•	PURPOSE OF FLIGHT: TECHNICAL OFFICER'S REPORT:	(
(	Progress Test on pupil  NATURE OF ACCIDENT: Instructor ordered pupil to carry out forced landing. at 800° throttles were opened to clear engines both of which gave full boost and R.P.M. At 250 ft. pupil was ordered to take overshoot action, both throttles were opened normally but engines failed to respond. Instructor was unable to start engines and landing was carried out with U/C retracted.  Pupil apparently choked engines by opening the throttles too hurriedly, engines were allowed to tick over too slowly.  COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:  SUMMARY NO.  (A) A D A D A D A D A D A D A D A D A D A	·. (
(	CLASSIFICATION: (	
(	54. Engine failure in the air.	,
(	17. Foucid Landing  SECONDARY OR CONTRIBUTORY FACTORS:	
€	14. Mishandling of controls  32. Pilot error  ACTION TAKEN:  Nil	·

C. C. LTD. 7084-43