

Nature of accident: Returning to land at M.A. was much too high. Started to go round again but engine failed through exhaustion of tank in use, while he was at about 200' over windward side of aerodrome. Glided on, going slowly and stretching the glide, Stalling in attempt to avoid high tension wires ground ahead being rather rough. At 50' he was near the Camp's high tension line and may have seen it suddenly for he stalled in on a turn 15 yards on fair side of cables. CLASSIFICATION: CLASSIFICATION: CLASSIFICATION: SECONDARY OR CONTRIBUTORY FACTORS: 32. Pilot error. ACTION TAKEN: NIL COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: FINDINGS: SUMMARY NO. 2192 Fuel shortage in the tank in use, and fuel cock not turned over. Forced landing attempted. Fuel shortage in the tank in use, and fuel cock not turned over. Forced landing attempted. SECONDARY OR CONTRIBUTORY STACTORS: ACTION TAKEN:	Routine solo.	CHNICAL OFFICER'S REPORT:
CLASSIFICATION: Pilet error in not changing to full gas tank. Note: There is no evidence that the port fuel tank contained gasoline but the conclusion is based on the presumption that it did. SECONDARY OR CONTRIBUTORY FACTORS: 32. Pilet error Pilet error in not changing to full gas tank. Note: There is no evidence that the port fuel tank contained gasoline but the conclusion is based on the presumption that it did.	Returning to land at M.A. was much too high. Started to go round again FIN out engine failed through exhaustion of tank in use, while he was at about 200' over windward side of aerodrome. Glided on, going slowly and stretching the glid ground ahead being rather rough. At 50' he was near the Camp's high tension line and may have seen it suddenly for	Cause Fuel shortage in the tank in use, and fuel cock not turned over. Forced landing attempted. Stalling in attempt to avoid high tension wires and posts. Recommendations. Nil.
based on the presumption that it did. SECONDARY OR CONTRIBUTORY FACTORS: 32. Pilot arror		Pilet error in not changing to full gas tank. Note: There is no evidence that the port fuel
32 Pilot arror	9. Out of Control 19	based on the presumption that it did.
		TON TAKEN.