

· · · · · · · · · · · · · · · · · · ·)) ·
) PURPOSE OF FLIGHT: TECHNICAL OFFICER'S REPORT:)
Practicing steep turns and single-engine flying. Nature of ACCIDENT:)
) Pilot was engaged on local flying, COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: FINDINGS: SUMMARY NO. 2100)
engine flying. A/C was observed to spin and crash on to Galiano Island and burnt out, the pilot being killed. A/C foll into a spin, from which the pilot was unable to recover and crashed. Cause: Obscure.)
engine flying practuce due either to pilot's inexp or rough air and the a/c had insufficient height in	
which to recover.	,)
CONCLUSIONS OF A.I.B.	-)
Cause: obscure. The pilot was flying below the minimum altitude authorized for the exercise)
√ CLASSIFICATION: involved.)
) 18. Loss of control) 23 Not known, 23)
SECONDARY OR CONTRIBUTORY FACTORS:)
) 23. Spinning.)
) 25. Inexperience. Nil)
R. C. A. F. L. 20 (Revised)) 7M-4-43 (3202) K. P. 5051 H. Q. 885-L. 20 C. C. LTD. 7084-43	з)
))