

PURPOSE OF FLIGHT:	TECHNICAL OFFICER'S REPORT:)
NATURE OF ACCIDENT:	Examination revealed that both sets of radius rods had been damaged due it is considered to a previous landing.)
'After completing authorized solo fli	ghtourt of inquiry or investigating officer's report)
) bobit tonud cust ale Monita not Tock	FINDINGS: SUMMARY No.)
down when he returned to aerodrome.		ì
After trying emergency system pupil	LUCKUPD	,
) signalled to ground that he was in difficulty and then came into land.	200/0/2)
Upon landing port u/c leg collapsed	and)
at end of run a/c settled down on po	rt	
) wing tip.		`
)		
, , , , , , , , , , , , , , , , , , ,)
CLASSIFICATION:)
) 21 II/C down but not 6,732, 7 12)
31. U/C down but not fully locked.	5	ì
) a facture		
SECONDARY OR CONTRIBUTORY FACTORS:		,
33. Technical defect.	ACTION TAKEN:)
35 W/C Defect. 26	ACTION TAKEN:)
) 93	Nil	
R.C. A. F. L 20 (REVISED) 7M-4-43 (3202) K. P. 5051		
H. Q. 885.L 20	C. C. LYD. 7084.43)
~)