

PURPOSE OF FLIGHT: Dusk Patrol Engine failure was caused by connecting rod of #3 cylinders breaking. NATURE OF ACCIDENT: Engine failed living off occasional COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: ) white puffs of smoke from exhaust portaindings: SUMMARY No. 21/2 Pilot announced his intention of baling CIRCUMSTANCES - "While in formation on Dusk Patro.") out. Gliding do n from 2500 ft. to engine failed and a/c dived out of control, and 1000 ft. a/c suddenly turned on its crashed and burned. right side and dove straight into the CAUSE - Engine failure caused by a structural ground leaving a trail of white smoke failure in a connecting rod which broke. from about 800 ft. down. RECOMMENDATIONS. Nil CONCLUSIONS OF AIB CLASSIFICATION: Agree with findingss This is the third failure of this type recently inti Packard Merlins where the journal had not been discoloured but the connecting rod had broken. The accident was due to the pilot stalling the a/c after complete engine failure. ACTION TAKEN: Nil.