

, ) ) ) ) ) <b>) ) ) ) ) ) ) ) ) ) ) ) ) )</b>	••••••••••••••••••••••••••••••••••••••
PURPOSE OF FLIGHT:	TECHNICAL OFFICER'S REPORT:
1st. Solo X Country Flight.  NATURE OF ACCIDENT:	Failure of saddle bolts on No. 2 Cylinder Head.
On return trip to base while on a solo X country, the engi e started to solo X country, the engi e started to suibrate. The oil pressure and temperature were above the maxium and the engi e failed to have sufficient power to maintain altitude and airsemanded and airsemanded to locate the cause for this behaviour, the student made a success forced landing.	COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:  SUMMARY No.  deed
CLASSIFICATION: 54. Engine failure in the air.	
SECONDARY OR CONTRIBUTORY FACTORS:	
33. Technical defect.	ACTION TAKEN: This pupil exhibited excellent airmanship in landing his a/c safely. His coolness, good procedure and
R. C. A. F. L 20 (REVISED) 7M.4-43 (3202) K. P. 5051 H. Q. 885-L 20	flying are worthy of raise.