

	, , ,	,
) PURPOSE OF FLIGHT: TECH) Dual instructions.	INICAL OFFICER'S REPORT:	
) NATURE OF ACCIDENT:	NIIICA/PCZ/XF	
Occupants of a/c 1142, F/O Grest and COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: LAC Henderson were flying in a north FINDINGS: SUMMARY No. 2193 Bully direction, at an altitude of 3500' Cause Lac Henderson was receiving instrument Collision caused by pilot error on part of both flying. Occupants of a/c 5944 were pilots in failing to keep proper lookout. Possib- flying in a northwesterly direction. From ility that hooded practices were being carried damage toca/c caused in flight, a/c 5944 out in a fairly congested area cannot be over-		
struck a/c 1142 at the trailing edge of stbd wing near fuselage. Both a/c were seen to descent together momentarily and then seperate. F/O Grest parachuted from a low altitude. CLASSIFICATION:	a/c immediately following collision in air	
26. Collision in the air. 21 Callising-ACZ/	where a/c cannot be controlled. Conclusions of A.I.B. Agree with findings.	
SECONDARY OR CONTRIBUTORY FACTORS:)	
ACTIO	ON TAKEN:	
*)	
)	Nil ,	
R. C. A. F. L 20 (REVISED)) 7M-4-43 (3202) K. P. 5051 H. Q. 885-L 20	C. C. LTD. 7084.43	
))))))))))))))))))) 		