

PURPOSE OF FLIGHT:	TECHNICAL OFFICER'S REPORT:
NATURE OF ACCIDENT: A/C APPROACHING TO LAND CAUGHT FIRE BEHIND PORT ENGINE. INSTRUCTOR PILOT LANDED A/C SAFELY AND WHEN 2/3 DOWN RUNWAY INSTRUCTOR ORBERED PUPP TO BAIL OUT AND BAOLED OUT HIMSELF, WHILE A/C WAS IN MOTION AND WERE INJURED. CRASH CREW EXTINGUISHED THE FIRE. CLASSIFICATION: 7 Athur 7 Athur	SEE BELOW LM/EF/M/L/M/L/MF/LA
	LITTLE DELAY AS POSSIBLE. CONCLUSIONS OF A.I.B.: I AGREE. THIS & THE FIRST FIRE SINCE THE REFITTING OF THE OLD EXHAUST SYSTEM TO MEET WINTER CONDITIONS. SENCE THE ACCIDENT, No. 4 T.C. HAS ORDERED THE UNITS TO REVERT TO THE TEMPORARY EXHAUST SYSTEM USED DURING THE SUMMER WHICH SUPPLIES NO CABIN HEATING. EVERY EFFORT SHOULD BE MADE TO SUPPLY AND FIT THE NEW MODIFICATION E.1/22/34 AS THE LOWERING OF PHYSICAL EFFICIENCY DUE TO UNHEATED CABINS MAY LEAD TO SERIOUS ACCIDENTS.
SECONDARY OR CONTRIBUTORY FACTORS:	ACTION TAKEN: