

)))))))))
ſ	PURPOSE OF FLIGHT:	TECHNICAL OFFICER'S REPORT:
) Practise Landings.	Nil
	NATURE OF ACCIDENT:	DS//22
1	Pupil turmed a/c into wind,) opened throttle, raised tail became airborme, hood slipped	COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: FINDINGS: SUMMARY No.)
	back, closed throttle, a/c settled down, swung to right and nosed over. CLASSIFICATION: ZZ. Pilot Error. M. Atler SECONDARY OR CONTRIBUTORY FACTORS:	Remarks of Unit C.O. Inexperience cauded pupil to mishandle the controls when his canopy flew back at commencement of take off. A little more care in fastening the canopy before take off might have prevented it from flying back which would have allowed the emergency to be prevented. A check of strap fastenings has been instructed.
)	ACTION TAKEN:
) R.C.A.F. L 20 (REVISED) 7M.4-43 (3202) K.P. 5051	Personal admonition by C.F.I.
	H. Q. 885.L 20	C. C. LTD. 7084-43
Ļ		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,