



PURPOSE OF FLIGHT:

Flying Instruction.

TECHNICAL OFFICER'S REPORT:

Failure of Lever, inner Elevator occurred by shearing of four rivets attaching this lever to socket Centre.

NATURE OF ACCIDENT:

While demonstrating steep turn, pressure on control column disappeared, and all elevator control was lost, & a/c went into a dive. After ordering F/O Rose to jump, Pilot made a successful landing by means of the tail trimmer.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

*1A/18/A10*

CLASSIFICATION:

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL.