

	/ <b>&gt;&gt;&gt;&gt;&gt;&gt;&gt;&gt;&gt;</b>
PURPOSE OF FLIGHT: Seq. 10,11,12,13,16,17.  NATURE OF ACCIDENT:	TECHNICAL OFFICER'S REPORT: No technical failure, but probable cause due to gas valve not being fully open. Gas shut off rod in cockpit found to be binding.
Student was taking off when engine failed at 50' and student turned cross wind into only available field which had considerable snow, and student a/c went over on its back.	COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:  FINDINGS:  SUMMARY NO.  d,  Remarks of Unit C.O.  With Engineer's report as above it is possible that cockpit lever showed fully on, when actually the shut off valve had not been completely open due to the binding. Error in judgement, in that student felt sure that the gas cock was fully on.
CLASSIFICATION:  13. Engine failure.  15. Janeed land.  SECONDARY OR CONTRIBUTORY FACTORS:	) )
37. Overturning.  R. C. A. F. L 20 (REVISED)	ACTION TAKEN:
7M-4-43 (3202) K. P. 5051 H. Q. 865-L 20	C. C. LTD. 7084.43