

TECHNICAL OFFICER'S REPORT PURPOSE OF FLIGHT: Solo practice. ) NATURE OF ACCIDENT: Both pilots practising forced land-COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: ings, interlocked and crashed. SUMMARY NO2229 FINDINGS: Two a/c collided at relatively low CAUSE: Aerial collision, probably due to the fact ) height, i.e. apparently under 1.000 that the pilot of each a/c involved may have been above ground level, over the leeward intent on watching the field on which he was making side of a stubble field suitable for a forced landing approach and that each failed to ) forced landings, the two a/c spiralling notice the other a/c, at any rate, until too late or spinning onto the field, the surface to take avoiding action, although it may possibly be of which was hard frozen. but this seems less probable that the pilot of one a/c was unable to see other a/c due to postion of each relative to one another and to the sun. CLASSIFICATION: RECOMMENSATIONS Continued urging on pilots of all a/c particularly on trainees that they must keep a constant look out, and that if any a/c ap ears to be practicing sequences of any sort in the near vicinity. the pilot observing such practice should not himselt SECONDARY OR CONTRIBUTORY FACTORS: continue practicing seq. in the vicinity. ACTION TAKEN: CONCLUSIONS OF A.I.B. Pupil pilots of these s/c both probably Nil failed to keep a proper look out. R. C. A. F. L 20 (REVISED) 7M-4-43 (3202) K. P. 5051 C. C. LTD. 7084-43