

PURPOSE OF FLIGHT: TECHNICAL OFFICER'S REPORT: Seq. 13.19.21.22. No indication of any failure which would cause loss of R.P.M. NATURE OF ACCIDENT: Flying downwind at 100' in low COURT OF INQUIRY OR INVESTIGATING OFFICER'S REF flying area, engine suddenly started missing and could only get 1400 R.P.M FINDINGS: SUMMARY No. by manipulation of throttle, therefore Findings of Investigation by No. 1 T.C. not enough power to maintain height. From evidence of witnessess, it would appear that Without sufficient height to maneouvre pilot could have been attempting a genuine forced sideslipped at 80 M.P.H. downwind in landing. However Chief Engineer can find no indendeavour to get into best field ication of defect or failure in engine. On basis available from height specified. Due of limited evidence would categorize this accidto snow covered ground misjudged ent as "obscure". Assuminga normal forced landheight and sideslipped in. ing, and as pilot misjudged height due to snow covered surface, his log book is being endorsed CLASSIFICATION: "Error in judgement" and no disciplinary action is being taken. SECONDARY OR CONTRIBUTORY FACTORS: rouble- Occident ACTION TAKEN: Log book endorsed "Error in judgement".

C. C. LTD. 7084-43

R. C. A. F. L 20 (REVISED) 7M-4-43 (3202) K. P. 5051 H. Q. 885-L 20