



PURPOSE OF FLIGHT:

S.B.A. exercise.

TECHNICAL OFFICER'S REPORT:

LS/ANT/PSS/ARD/XC77

Failure of Beam approach receiver due to breakdown of by-pass condenser in H.T. circuit in R1124C. This c used a high tension shor circuit and blew the H.T. fuse.

NATURE OF ACCIDENT:

Upon landing in zero visibility and with Beam equipment in a/c u/ R. stbd wheel converged into snowbank causing a/c to swing and nose up.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~2. Technical defect.~~

2 18 Misc. Technical

SECONDARY OR CONTRIBUTORY FACTORS:

~~2. Hitting obstructions.~~

~~AA~~

ACTION TAKEN:

NIL