

61 () 60 () 59 () 58 () 57 () 56 () 55 () 54 () 53 () 52 () 51 () 50 () 49 () 48 () 47 () 46 () 45 () 44 () 43 () 42 () 41 () 40 () 39 () 38 () 37 () 36 () 35 () 34 () 33 () 32 () 31 ()

ACCIDENT CLASSIFICATION

UNIT 32 O.T.U. Pat. Bay.	COM. WAC	PLACE Boundary Bay Aerodrome, B.C.	DATE 19-2-44	TIME 2020		
A/C TYPE BEECHCRAFT UC45B		NO. HB.105 HB. 135-D	CRASH CAT. "D" "E"	H.Q. FILE 1300-UB105		
PERSONNEL		RANK	NUMBER	DUTY	INJURIES	SIGNAL
Webb, D.J.		F/O	141479	P	Uninj.	NO. DATE
Raffan, J.T.		F/L	90938	P	Uninj.	NO. DATE
						D 14 (REVISED)
						NO. CHECKED

COMMAND

MONTH

STAGE OF FLIGHT

7
4
2
1
7
4
2
1
Forced Landing
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INI.
3RD
INJURY
5
4
3
2
1
RAF

TYPE OF A/C
TYPE OF UNIT
CATEGORY

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
Wasp Junior	P. AC/42/23346 S. AC/42/23547 P. AC/42/122318 S. AC/42/122482	INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
		60	56	24	3	546	170
		36	63	18	5	1124	160

#2^{OR} 2/2

ACCIDENT CLASSIFICATION

1 () 2 () 3 () 4 () 5 () 6 () 7 () 8 () 9 () 10 () 11 () 12 () 13 () 14 () 15 () 16 () 17 () 18 () 19 () 20 () 21 () 22 () 23 () 24 () 25 () 26 () 27 () 28 () 29 () 30 ()

PURPOSE OF FLIGHT:

Night Circuits

TECHNICAL OFFICER'S REPORT:

NIL

TCA / PCL

MULT ✓

NATURE OF ACCIDENT:

Beechcraft HB. 105 was parked near end of Runway waiting for permission to taxi on to Runway and take off, when Beechcraft HB. 135 taxied up behind and collided.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~3. Hitting other Aircraft.~~

9. collisions

9

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL