

PURPOSE OF FLIGHT:	TECHNICAL OFFICER'S REPORT:
Dual instruction on instrument flying	· Nil /CA/PCL/I Commerced
NATURE OF ACCIDENT:	ICA/POLIVYA
Captain of a/c FH868 was teaching PP air speed control. Dove a/c to approx. 130 MPH on straight course gave over control to PP, and almost	COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: FINDINGS: SUMMARY No.
captain of a/c 10517 was climbing straight and above clouds with PP in control, under hood, when he saw othe a/c, collided with it and was unable	r
to avoid it. Both a/c were approx. on same heading at time of collision. A/C 868 was flown back to Rl at Lethb CLASSIFICATION: while other a/c made a forced landing in the	urn successful
26. Collision in the air. 21 Collision in the air. SECONDARY OF CONTRIBUTORY FACTORS:	
	ACTION TAKEN:
R.C.A.F. L 20 (REVISED) 7M-4-43 (3202) K.P. 5051 H. Q. 885-L 20)))))))))))))))))))	C. C. LTD. 7084-43