

	PURPOSE OF FLIGHT:	TECHNICAL OFFICER'S REPORT:	
		Cyl barrel broke all round at distance of 1 3/4 inch	,
L.,		from top of barrel, so that cyl head was held in place only by baffle support bridges.	ይ <i>ጎ</i>
	5 mins. after take-off, pilot notice		,
	smoke coming from top of engine.	COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:)
	This continued for a few mins. and en	ngine SUMMARY No.	
$ \ge $	started to knock and pilot turned	FB/AOP/F3/MP/Q/I)
	back, but as speed was dropping he		
1	decided to execute forced landing. Engine started to knock badly, so		٠,٠
-	engine was shut off and safe forced		ز.
ر د آ	landing was made in muddy field.		ر
)	A/C was flown back to base, after)
)	cylinder changed.)
ر	CLASSIFICATION:)
)			``
	17. Forced landing.		,
)	SECONDARY OR CONTRIBUTORY FACTORS:)
	27. Engine trouble-no damage.)
)		ACTION TAKEN:)
)		Nil ·	ر د
	R, C, A. F. L 20 (REVISED)		ر.
/	7M-4-43 (3202) K, P. 5051 H. Q. 885-L 20	C. C. LTD, 7084.43)
)) /)))))))))))))