

LIREOSE OF FLIGHT: TECHNICAL OFFICER'S REPORT: Might Rombing Exercise. TATURE OF ACCIDENT: C are shed immediately after take-of EOURT OF INQUIRY OR INVESTIGATING OFFICER'S REPOR about 600 rds off end of runway 12. FINDINGS: SUMMARY No. 2233 Pilot states crash not due to airframe CAUSE: Pilot error. (1) On Becoming airborne, pilot or engine Eatlure but that he relaxed diverted his attention from instruments in order to his attention from his instruments determine location of a/c which had proceded him on momentarily to look ahead and crashed take-off. Without further reference to his instruimmediately afterwards. ments he then depressed the nose of a/c allowing a/ to strike water. (2) A/C maintance and local flying orders were complied with. (3) All occupants of a/o were on duty at time of accident. (4) Court had been able to establish authority for additions to the CLASSIFICATION: F.17 Court is satisfied from comparison with exist ing signatures of LAC Campbell in old Forms. L.14 that the deceased edded his own name to F.17. DATICARY For Recommendations see Sunnary 2433. COCCUSIONS OF A.L.B.: Agree with the finding SECONDARY OR CONTRIBUTORY FACTORS: ACTION TAKEN: L. C. A. F. L 20 (REVISED)