

PURPOSE OF FLIGHT: TECHNICAL/OFFICER'S REPORT: Routine transportation of fraight to aoc/PCDM Norman Wells, N.W.T. NATURE OF ACCIDENT: M/C took off with flaps in the COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: "down" position, gained approximately SUMMARY No. 2505. 150 height, travelling some three CAUSE: Taking off with flaps down. Failure to miles and. after losing altitude. maintain fall power after take-off. ) stalled. and struck the ground. RECOMMENDATIONS: NAI stbd. wing first. REMARKS CE C.O.: (a) Forgetfulness - He did not ensure during cockpit check prior to take-off, that flaps were in up position. (b) Error in judgement He, having been informed flaps were in down positions continued to become airborne when it is considered according to evidence shown sufficient distance was available to effect a stop before reaching end of CLASSIFICATION: runway or coming in contact with obstacles, REMARKS OF C.O. : D concur. CONCLUSIONS OF A.I.B.: Incomplete cockpit drill before take-off. SECONDARY OR CONTRIBUTORY FACTORS: **ACTION TAKEN:** F. L 20 (REVISED)