

PURPOSE OF FLIGHT:	TECHNICAL OFFICER'S REPORT: FB RODES MP 3
14-16-17-22- 12-13. NATURE OF ACCIDENT:	Cylinder head of Mo. 1 Cylinder had a crack about 3" long.
While student was practicing steep turns engine missed badly. Student closed throttle and then slowly opened again, but engine still missed. Oil fumes were very bad in cockpit, consequently carried out a forced landing successfully.	
CLASSIFICATION: 17. Forced Landing.	
SECONDARY OR CONTRIBUTORY FACTORS: 26. Engine Trouble - Accident.	ACTION TAKEN:
R. C. A. F. L 20 (REVISED) I.M.6.45 (4999) K. P. 36374	Ni 1