

PURPOSE OF FLIGHT: TECHNICAL OFFICER'S REPORT: IM ) Bombing Trial Loss of fuel pressure. NATURE OF ACCIDENT: Both engines cut almost simultaneously OURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT: FINDINGS: SUMMARY No. selectors and switching on auxiliary fuel pump, the engines failed to pick CAUSE: Total engine failure due to lack of O up. Pilot ordered the crew to abandon fuel at engines. Lack of fuel reaching engines the a/c and abandoned it himself. obscure, but strong possibility due to pilot's inexperience on type. CONCLUSIONS OF INVESTIGATING OFFICER: This Unit was not adhering to pilot's operating instructions for Boston a/c, in that they were using main tanks for run-up-take-offs, climb, flight CLASSIFICATION: and landing, whereas these instructions provide 18. Misc. Technical that these run-up takeoff climb & landings are to be on mains while flight in to be on aux. tanks thus conserving fuel in main tanks for final operation and landing. Both F/O Symes & F/S SECONDARY OR CONTRIBUTORY FACTORS: ACTION TAKEN: Miller abandoned incorrectly; feet first instead of head first. R. C. A. F. L 20 (REVISED) 1M.A.45 (4999) K. P. 36374 H. Q. 885-L 20