

```
MULT: MAIXEM
DUTY ON WHICH ENGAGED:
                                        COURT OF INQUIRY, INVESTIGATING OFFICER
Ferrying A/C from TRENTON to NO.
                                        OR COMMANDING OFFICER'S REPORT:
2 T.C.
                                          Court of Triquiry (File 1100-40-45) MAX
NATURE OF ACCIDENT AND STAGE OF FLIGHT:
                                        DATE:
                                                29-6-40
                                        COMPOSITION:
On the ground running up A/C.
wing of 4045 collided with airscrew
                                                President - S/L R.H. Little
of A/C No.4049, then propeller
                                                   Member - F/O C.G. Durham
of 4045 hit wing of 4049.
                                                   Member - F/O E.G. Pafford
                                        RECOMMENDATIONS:
                                             That all ranks observe and carry out in-
                                             structions in para.26(iii) and (iv) A.P. 129-
PRIMARY CAUSE:
                                             Flying Training Manual.
(3) Negligence on part of pilot of
 A/C No.4045, T/Sgt. Gillespie, in
 not carrying out instructions re-
 garding starting motor in accord- ACTION TAKEN:
                                          (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
 ance with A.P. 129.
                                           No.1 T.C. advised:
                                           (a) T/Sgt. Gillespie to be warned
                                           (b) Nature of accident and consequences to be
                                               promulgated throughout Command. O/C Ferry
                                               Flight - did not exercise suitable supervision-
SECONDARY CAUSE OR CONTRIBUTING FACTORS:
                                               allowed flight to take place without proper maps.
(1) Lack of equipment and detailed instructions before commencement of
                                               H.Q.1100-40-45 d/24-7 RECORDED BY
flight. (2) Lack of supervision by Officers i/c during flight.
                                                                       CHECKED BY
```