

WTY ON WHICH ENGAGED:	OR COMMANDING OFFICE'S PEDORT. 786/ANT/PEP/UBF
Anti-Aircraft	ON COMMANDING OFFICER S REPORT
ATURE OF ACCIDENT AND STAGE OF FLIGHT:	Investigating Officer's Report D.13  DATE: 24-8-40
Taxiing-while taxiing along	COMPOSITION:
runway, brakes were fully	
applied but to no avail.  Aircraft rolled into ditch and	Flt. Lt. D.G. Price (C.156)
nosed over, damaging prop and	RECOMMENDATIONS: Pilots to be instructed through the
wheel housing.	medium of unit standing orders, that the pressure
RIMARY CAUSE:	in the tank must not be allowed to fall below 100 lbs. If necessary the A/C is to be stopped
Due to pilot persisting in	and the engine run to maintain the 100 lbs.
taxiing the aircraft down and	pressure.
cress wind with insufficient air in the braking system.	ACTION TAKEN:
all in the blaking system.	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
	D.13 approved by A.M.A.S. 16-9-40
	· · · · · · · · · · · · · · · · · · ·
ECONDARY CAUSE OR CONTRIBUTING FACTORS:	
	RECORDED BY DATE
	CHECKED BY DATE