

	Buty on which engaged: Harbour entrance patrol	OR COMMANDING OFFICER'S REPORT:	)
)	marcour engrance bactor	Commanding Officer's Report - D.14	
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: 29-8-40	)
)	Aircraft bounced during take off	COMPOSITION:	
h	in ground swells	•	
,		Wg. Cmds. W.W. Brown	)
)			)
)		RECOMMENDATIONS:	
ì		In view of the necessity of using bolta aircraft	نس
i h	PRIMARY CAUSE:	at North Sydney, no reasonable recommendation can be made.	
) 	Due to the existence of a mild	Call be wate.	-
)	ground swell which the O.C. and		)
)	the experienced pilot did not		<b>-</b>
'n	consider would affect the normal	ACTION TAKEN:	3
7	take off, the aircraft left the	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	ر
1	water before sufficient speed was		)
)	attained and bounced.		
)			
}	SECONDARY CAUSE OR CONTRIBUTING FACTORS:		``
1 1.			J
1		RECORDED BY DATE	
)		<del>-</del>	)
)			)
		CHECKED BY DATE	ر
1			

`