

5	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER TIFINAL AT A LOS OFFICE
)		OR COMMANDING OFFICER'S REPORT:
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:
つ つ	Forced landing from engine failure, overshot field and turned over on back.	COMPOSITION: D.A. Harding, Squadron Leader.
)		RECOMMENDATIONS:
)	PRIMARY CAUSE: Engine failure.	No recommendations as failure was the result of defective engine part (Tappet) Cam Follower.
))		ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
C		
)) SECONDARY CAUSE OR CONTRIBUTING FACTORS: As stated in our phonogram No.17 dated 2-9-40, the Instructor (Mr.A.J. Williams) evershot the field in making a forced landing	
)	after the engine failed at 1000 ft. coming in contact with rough ground))))))))))))	and when