

		The state of the s
,\$	() () () () () () () () () () () () () (
)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
)		OR COMMANDING OFFICER'S REPORT:
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:
)	Landing wheel fell off on take	COMPOSITION:
)	off, left axle dragged 40 feet	
)	before plane turned over on back.	
)		RECOMMENDATIONS:
-		
•	PRIMARY CAUSE:	•
)	Faulty manufacture of axle	
3		
)	•	ACTION TAKEN:
)		(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
5		1 T.C. 1935-AE-4511 d/11-11-40 on 1100-45-11
)		"a simple fitting was made up at this Command and distributed to alleschools concerned with in-
ر د	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	structions regarding the installation."
`		Min.2 on above letter: "Noted - modification action
ر د		is now being taken. WA.N.A.E. 18-11 RECORDED BY DATE
ر `		
.) 		CHECKED BY DATE
)))) [))))))))))))))))))))))))