

being warmed up by apprentice mechanic Carey. NATURE OF ACCIDENT AND STAGE OF FLIGHT: The apprentice mechanic had the switches in the ON position when the starter battery was being plugged in by another mechanic. The aircraft lunged forward and collided head on	RECOMMENDATIONS: Stricter supporting a .
PRIMARY CAUSE: Ignorance on the part of the apprentice mechanic. Negligence on the part of the operating company in not strictly supervising inexperiemechanics.	C.S.C. inform the Manager of the Operating Company that every step should be taken to ensure proper supervision of the staff. CION TAKEN:
) SECONDARY CAUSE OR CONTRIBUTING FACTORS:	(A) Disciplinary (B) Technical (C) Other .14 approved by A.M.T. 21-1-41.
)))))))))))))))))	CHECKED BY DATE)