

0 302 3 3 3 3 3 3 3 3 3 3 3 3 3 DUTY ON WHICH ENGAGED: COURT OF INQUIRY, INVESTIGATING OFFICER. AR Gunnery OR COMMANDING OFFICER'S REPORT: training. INVESTIGATING OFFCIER'S REPORT. NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE: (9-12-40)COMPOSITION: Engine failure. WHER FLYING AT A HEIGHT OF IF 800 FEET THE ENGINE FALTERED Flight Lieutenant M.C. Stadden. AND THEN STOPPED. THE PILOT THEN MAINTAINED AN INTERRUPTED POWER GLIDE AND MANAGED TO RECOMMENDATIONS: Closer check on gas condition with MAKE A CROSS-WIND LANDING ON THE NORTH EAST litmus paper and samples in gas trucks in gas tanks PART OF THE EMERGENCY LANDING FIELD AND in aircraft and closer checks on aircraft strainers WITH THE UNDERCARRIAGE RETRACTED. D/DED does not concur with the findings of the EVIDENCE OF THE COURT WAS THAT THERE Court and requests A.M.T call for exmaminations to WAS A MECHANICAL FAILURE DUE TO A be properly carried out in the case of accidents caused RESTRICTION IN THE GAS LINE BETWEEN THE by engine failure. para. 5 1100-16-81 of 11-2-41. FUEL PUMP AND THE CARBURETTOR. (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Recommendations of D/DED carried out. A.M.T. approves D.13 on 24-2-41 with letter on same date. on file 1100-16-81. SECONDARY CAUSE OR CONTRIBUTING FACTORS: RECORDED BY DATE CHECKED BY DATE