

DUTY ON WHICH ENGAGED: COURT OF INQUIRY, INVESTIGATING OFFICER LRG/ATO/PCDE/XGS/ OR COMMANDING OFFICER'S REPORT: Flying instruction. Commanding Officer's Report NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE: 17-12-40 COMPOSITION: Aircraft landed on soft show portion of field and over-Flight Lieutenant H.C. Ledoux. The pilot had undershot the field and he attempted to throttle COMMENDATIONS: up the engine, the engine did not Instructor and pupil warned to exercise respond immediately with the result that he landed on the uncompacted / greater care when opening throttle, after fliding and also not to wait too long, whe part of the aerodrome. undershooting, before opening throttle. The pilot undershot the aerodrome Suitable markers have been installed to due to the difficulty of judging height and distance because of indicate the serviceable portion of the **ACTION TAKEN:** bright snow glare. aerodrome. (A) DISCIPLINARY (B) TECHNICAL (C) OTHER D.14 approved by A.M.T. 17-12-40 SECONDARY CAUSE OR CONTRIBUTING FACTORS: Landed on uncompacted portion of the field. RECORDED BY DATE CHECKED BY