

DUTY ON WHICH ENGAGED:	COURT OF INCHIEV INVESTIGATING OFFICER
Gunnery Exercise	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:
-	
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: 21.1.42 **INVESTIGATING OFFICER'S REPORT**
Aircraft 1692 was taxing along	COMPOSITION:
taxi strip after completion of Gunnery Exercise. In order to	-1
avoid a towed aircraft in front,	F/O A.C. TAYLOR
pilot swung 1692 to the right	
missing towed aircraft but collider	RECOMMENDATIONS:
) with refuelling tender parked in	ite _
usual place. After successfully	Continue to impress upon pilots the
1692 moved on to an icy surface w	necessity of taxing their aircraft
turn and brakes were of no avail.	at a safe speed and in a safe manner.
THE MY SERVING STATES OF THE PROPERTY OF THE	189
PRIMARY CAUSE: - Carelessness on the part of the pilot in that he faile	
part of the pilot in that he faile	ACTION TAKEN:
	od
part of the pilot in that he faile to keep his aircraft under complete	ACTION TAKEN:
part of the pilot in that he faile to keep his aircraft under complete	ACTION TAKEN: COTA) DISCIPLINARY (B) TECHNICAL (C) OTHER
part of the pilot in that he faile to keep his aircraft under complete	ACTION TAKEN: COTA) DISCIPLINARY (B) TECHNICAL (C) OTHER
part of the pilot in that he faile to keep his aircraft under complet control while taxiing.	ACTION TAKEN: COTA) DISCIPLINARY (B) TECHNICAL (C) OTHER
part of the pilot in that he failed to keep his aircraft under complete control while taxiing. SECONDARY CAUSE OR CONTRIBUTING FACTORS: Aircraft came into collision with	ACTION TAKEN: COTA) DISCIPLINARY (B) TECHNICAL (C) OTHER
part of the pilot in that he failed to keep his aircraft under complet control while taxiing. SECONDARY CAUSE OR CONTRIBUTING FACTORS: Aircraft came into collision with refuelling tender #821, parked in	ACTION TAKEN: COTA) DISCIPLINARY (B) TECHNICAL (C) OTHER
part of the pilot in that he failed to keep his aircraft under complete control while taxiing. SECONDARY CAUSE OR CONTRIBUTING FACTORS: Aircraft came into collision with refuelling tender #821, parked in its usual location on the hangar	ACTION TAKEN: COTA) DISCIPLINARY (B) TECHNICAL (C) OTHER N11
part of the pilot in that he failed to keep his aircraft under complet control while taxiing. SECONDARY CAUSE OR CONTRIBUTING FACTORS: Aircraft came into collision with refuelling tender #821, parked in	ACTION TAKEN: COTA) DISCIPLINARY (B) TECHNICAL (C) OTHER N11