

5	() () () () () () () () () () () () () ())))	333	5 5))	3)) 3))	3	
)	DUTY ON WHICH ENGAGED:	COURT OF INQUI	RY, INVESTIG	SATING OF	FICER	<u>.</u> .)
)	Starting motor up prior to take off.	OR COMMANDING	OFFICER'S	REPORT:		R170					-
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:	TM								
	Mechanics left arm was struck	COMPOSITION:	-								•
)	by propellor blade during start- ing procedure.										•.
)	ing procedure.))
)		RECOMMENDATIO	ons:		-						
)		Nil	r.							1	Ė
)	PRIMARY CAUSE:										5
)	24. Prop.									;	
)	·	ACTION TAKEN:	•)
)	- 1	(A) DISCIPLINAR	Y (B) TECHN	ICAL (C)	OTHER)
) `	74)
<i>)</i>		Nil)
ノ ハ	SECONDARY CAUSE OR CONTRIBUTING FACTORS:) `
ノ コ											ر ر
ノ ゝ	Mechanic struck by propeller.				RECO	RDED BY			DATE	-)
ノ コ					CHEC	KED BY			DATE	_	``
ノ)))))))	2.2.2.2		3.3))) ;)))	· •	DATE	`	ノ
				<i>J</i> \ <i>J</i>	, , , , , , , , , , , , , , , , , , ,	., ,	. 		, .))	