

1))))))))))))))))))))))))))))))))))))))))
)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OF	FICER		Ç
)	Starting the engine.	OR COMMANDING OFFICER'S REPORT:			·
	NATURE OF ACCIDENT AND STAGE OF FLIGHT: Engines of a/c were being started up and propellor was being turned. Apparently one of the pistons of the engines must have been on top dead centre as the booster coils were brought into action spark occurred causing engine to start. Propellor struck the airman in the	DATE: COMPOSITION: RECOMMENDATIONS:	vestigating	Officer's Repor	
	PROP. (groin.	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C	C) OTHER)))
つううう	SECONDARY CAUSE OR CONTRIBUTING FACTORS:		RECORDED BY	DATE)
))	R.C.A.F. FORM L20 REQ. 1247 10M—15-11-41)))))))	CHECKED BY	DATE))))	2