

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFF	ICER			
Propellor swinging.	OR COMMANDING OFFICER'S REPORT:				_
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:		R.170		. ,
Propeller being swung by civilian	COMPOSITION:				7
employee for a night flying A/C test. Confused action by civilian					
who pulled prop over with two hands after getting contact. Engine	RECOMMENDATIONS:				-
fired and struck civilians hand.					-
PRIMARY CAUSE:	•				-
Confused propellor drill by		· •			-
untrained employee.					
Oxop.	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OT	THER			- 3
1241	Stricter instructions to civil employees.				
			•		-
					-
SECONDARY CAUSE OR CONTRIBUTING FACTORS:		- '			,
Engine fired during sucking in		RECORDED BY	•	DATE	
A TANK CIVILIANS NAME OF THE PARTY OF THE PA		WECOUPED BI	ta yan	PAIE	
	art Art	CHECKED BY		DATE	