

\mathcal{L}	3333333333 333333333333
) DUTY ON WHICH ENGAGED: COL	WIDT OF INCUIDATING OFFICER
Elight prostice	URT OF INQUIRY, INVESTIGATING OFFICER COMMANDING OFFICER'S REPORT:
<u>on</u>	D-14
NATURE OF ACCIDENT AND STAGE OF FLIGHT: DA	TE:
) While starting A/C 4409 owing to con	MPOSITION:
a misunderstanding of starting	,
order given, a switch was advanced	,
) to "ON" and as a result engine)
) started, striking ground man on bothmen	COMMENDATIONS:
hands, although doing no apparent	a
damage. PRIMARY CAUSE:	
,)
) Misunderstanding of order given.)
))
) AC	TION TAKEN:
	(A) Disciplinary (B) Technical (C) Other
AIT	er investigation pupil found not responsible.
•	
)	,
CECONDADY CAUCE OF COMPANY THE TARGET	,
Noise from nearby A/C and the fact)
that this groundman remained directly	RECORDED BY DATE
in front of A/C.	· · · · · · · · · · · · · · · · · · ·
,	·
J R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41	CHECKED BY DATE
)	