

(
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Taxiing from east side of aerodrom back to building area.	OR COMMANDING OFFICERING PERCENT
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:
While taxiing throttle of aircraft	
was open to such an extent that due	
to high winds, aircraft became air	-
borne. Control column being held	RECOMMENDATIONS:
fully back, aircraft flipped over and hit ground on starboard wing a	
then overturned on its back.	ma —
PRIMARY CAUSE:	
62. Taxiing too fast.	
÷	ACTION TAKEN:
	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
	Dismissal of ground crew mechanics, C. Drouin and
	L. Beaudoin.
CECONDARY CAUCE OR CONTRIBUTING PLOTORS	
SECONDARY CAUSE OR CONTRIBUTING FACTORS: A/C flipped over and hit ground	
on stbd wing and then overturned	RECORDED BY DATE
on its back.	
·	CHECKED BY DATE
R.C.A.F. FORM L20 REQ. 1247 10M—15-11-41	The state of the s
_ / / / / / / / / / / / / / / / / / / ,	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,